

TABLE OF CONTENTS

1.0	INTRODUCTION	1
1.1	OWNERSHIP	1
1.2	PROJECT LOCATION.....	2
1.3	SITE HISTORY.....	4
1.4	REGULATORY OVERVIEW AND REQUIREMENTS	5
1.4.1	REGULATORY BACKGROUND	5
1.4.2	MANITOBA ENVIRONMENTAL REVIEW AND APPROVAL PROCESS	8
1.4.3	ENVIRONMENTAL LICENCE ALTERATION PROCESS	9
1.5	LICENCES, PERMITS AND AUTHORIZATIONS	9
1.6	DOCUMENT ORGANIZATION.....	10
2.0	SCOPE OF THE NOTICE OF ALTERATION	11
2.1	SPATIAL BOUNDARIES.....	11
2.1.1	REGIONAL STUDY AREA	11
2.1.2	LOCAL STUDY AREAS.....	11
2.1.3	PROJECT SITE	11
3.0	PROJECT DESCRIPTION	16
3.1	GEOGRAPHIC LOCATION	16
3.2	MINERAL SURFACE RIGHTS.....	16
3.3	MINERAL RESERVE AND MINE LIFE	18
3.3.1	TANTALUM.....	18
3.3.2	SPODUMENE.....	18
3.3.3	POLLUCITE	18
3.4	MINE LIFE.....	18
3.5	SURFACE FACILITIES.....	19
3.5.1	TANCO MINE INFRASTRUCTURE	19
3.5.1.1	Head Frame and Portal	21
3.5.1.2	Mill and Dry Grinding Plant.....	21
3.5.1.3	Cesium Products Facility (Chemical Plant).....	21
3.5.1.4	CPF Residue Containment Cells and Residue Stockpile	21
3.5.1.5	Tailings Management Area.....	21
3.5.1.6	Waste Transfer Station.....	21
3.5.1.7	Power Transmission and Transformer Station	21
3.5.1.8	Storage Facilities	22
3.5.1.9	Quarries.....	23
3.5.1.10	Access Road and Parking Lot	23
3.5.1.11	Office, Warehouse and Mine Dry	24
3.5.1.12	Security Building.....	24
3.5.2	MOLSON LOADING FACILITY	24

3.6	MINING (TANTALUM, SPODUMENE, AND POLLUCITE).....	24
3.6.1	MINING METHOD AND PRODUCTION RATES.....	25
3.6.2	MINE OPENINGS AND VENTILATION.....	25
3.6.3	MINE EQUIPMENT	25
3.6.4	UNDERGROUND INFRASTRUCTURE	26
3.6.5	MINE WATER MANAGEMENT	28
3.6.6	MINING WASTE.....	28
3.6.7	CROWN PILLAR STABILITY.....	28
3.7	MILLING (TANTALUM, SPODUMENE, AND POLLUCITE).....	28
3.7.1	MILLING PROCESS	28
3.7.2	MILLING PRODUCTION RATE.....	29
3.7.3	MILLING EQUIPMENT	29
3.7.4	MILLING REAGENTS	29
3.7.5	MILLING WASTE.....	30
3.7.6	PRODUCT STORAGE AND TRANSPORTATION	30
3.8	TAILINGS MANAGEMENT.....	30
3.8.1	EAST TMA	31
3.8.2	WEST TMA.....	31
3.8.2.1	Dams and Control Structures	33
3.9	CESIUM PRODUCTS FACILITY	36
3.9.1	CHEMICAL PLANT EQUIPMENT	36
3.9.2	PRODUCT STORAGE AND TRANSPORTATION	36
3.10	CPF RESIDUE MANAGEMENT	37
3.10.1	CURRENT RESIDUE MANAGEMENT.....	37
3.11	WATER USE AND MANAGEMENT	40
3.12	SITE RUNOFF MANAGEMENT	42
3.13	WASTE MANAGEMENT	42
3.13.1	SOLID WASTE.....	42
3.13.2	SANITARY WASTE.....	43
3.13.3	HAZARDOUS WASTE	43
3.14	NOISE MANAGEMENT	46
3.15	OPERATION EMISSIONS AND MANAGEMENT	46
3.15.1	AIR.....	46
3.15.1.1	Greenhouse Gas Emissions.....	49
3.15.2	LAND.....	49
3.15.3	WATER.....	50
3.16	SITE SECURITY.....	60
3.17	MALFUNCTIONS OR ACCIDENTS.....	60
3.18	CONTINGENCY AND EMERGENCY RESPONSE PLANS	61
3.19	HEALTH AND SAFETY	61
3.20	SUSPENSION OF OPERATIONS.....	62
3.21	DECOMMISSIONING AND RECLAMATION	62
3.21.1	PLANNED DECOMMISSIONING ACTIVITIES.....	62
3.21.2	CPF RESIDUE MANAGEMENT AT CLOSURE	63
3.21.3	POST-CLOSURE MONITORING	63
4.0	EXISTING ENVIRONMENT	64

4.1	PHYSICAL ENVIRONMENT	64
4.1.1	TOPOGRAPHY	64
4.1.2	CLIMATE	64
4.1.3	SURFICIAL GEOLOGY	70
4.1.4	SOILS	70
4.1.5	HYDROGEOCHEMISTRY	70
4.2	TERRESTRIAL ENVIRONMENT	76
4.2.1	VEGETATION.....	76
4.2.2	WILDLIFE.....	78
4.2.3	RARE SPECIES	81
4.3	AQUATIC ENVIRONMENT.....	81
4.3.1	SURFACE HYDROLOGY.....	81
4.3.2	PHYSICAL LIMNOLOGY	82
4.3.3	WATER QUALITY	83
4.3.4	SHORELINE AND BOTTOM SUBSTRATE	104
4.3.5	SEDIMENT QUALITY.....	104
4.3.6	ZOOBENTHOS	113
4.3.7	MACROPHYTE DISTRIBUTION.....	115
4.3.8	LOWER TROPHIC LEVELS	115
4.3.9	FISH AND FISH HABITAT	120
4.3.10	FISH HARVEST	120
4.4	HUMAN ENVIRONMENT	121
4.4.1	REGIONAL AREA OF INTEREST	121
4.4.1.1	Municipalities	121
4.4.1.2	First Nations	122
4.4.2	REGIONAL ECONOMY	123
4.4.3	REGIONAL LABOUR FORCE.....	123
4.4.4	LAND USE	125
4.4.4.1	Provincial Parks.....	125
4.4.4.2	Resource Use.....	126
4.4.4.3	Traditional Use	126
4.4.5	ARCHAEOLOGICAL RESOURCES.....	126
4.4.6	LOCAL TRAFFIC	128
5.0	ENVIRONMENTAL IMPACT ASSESSMENT AND MITIGATION PLAN.....	129
5.1	EFFECTS OF CONTINUING OPERATIONS	129
5.2	AQUATIC RESOURCES.....	130
5.2.1	EFFECTS OF CPF RESIDUE PLACEMENT AND STORAGE IN THE EAST TMA.....	131
5.3	CONTINUING EFFECTS POST-CLOSURE	134
5.4	CUMULATIVE EFFECTS ANALYSIS	135
5.5	EFFECTS OF THE ENVIRONMENT ON THE PROJECT.....	137
5.5.1	CLIMATE CHANGE	137
5.6	ACCIDENTS AND MALFUNCTIONS	137
6.0	MONITORING PROGRAM.....	139
6.1	MMER EFFLUENT SAMPLING FOR DELETERIOUS SUBSTANCES AND PH.....	139
6.2	EEM: EFFLUENT CHARACTERIZATION AND WATER QUALITY MONITORING	141
6.3	EEM: BIOLOGICAL STUDIES	144

6.4	GROUNDWATER MONITORING	144
6.5	NATIONAL POLLUTANT RELEASE INVENTORY	147
7.0	PUBLIC ENGAGEMENT.....	148
7.1	OBJECTIVES	148
7.2	PUBLIC INVOLVEMENT ACTIVITIES.....	148
7.2.1	STAKEHOLDER IDENTIFICATION	148
7.2.2	MAIL-OUT.....	149
7.2.3	OPEN HOUSE	149
7.3	REGULATORY INVOLVEMENT	150
7.4	PUBLIC RESPONSE	150
7.5	CONTINUING COMMUNICATION	152
8.0	REFERENCES.....	153

APPENDIX A	ENVIRONMENT ACT LICENSE NO. 973 AND NOTICE OF ALTERATIONS
APPENDIX B	CURRENT LICENCES, PERMITS AND AUTHORIZATIOIS
APPENDIX C	MINE CLOSURE PLAN
APPENDIX D	MILLING PROCESS SIMPLIFIED FLOWSHEETS
APPENDIX E	CONSTRUCTION DRAWINGS OF MAIN DAM AND PERIMETER DYKES
APPENDIX F	AIR DISPERSION MODELING REPORT
APPENDIX G	DUST SURVEY
APPENDIX H	EMERGENCY RESPONSE PLAN
APPENDIX I	CPF RESIDUE HYDRO-GEOCHEMICAL ASSESSMENT
APPENDIX J	TANCO PUBLIC ENGAGEMENT CONTACT LIST
APPENDIX K	TANCO OPEN HOUSE ADVERTISEMENTS AND NOTIFICATION LETTERS
APPENDIX L	TANCO OPEN HOUSE DISPLAY BOARDS

LIST OF TABLES

Table 1.1	Effluent quality limits at the final discharge point. Units are in mg/L.....	6
Table 1.2	History of Environment Act Licence No. 973.	7
Table 3.1	Transformer voltage conversion and oil capacity.....	22
Table 3.2	Propane capacity by storage location.	23
Table 3.3	TANCO production data for 2005 to 2011.	25
Table 3.4	TANCO milling reagent use for 2006 to 2008 (units are kg).....	30
Table 3.5	Chronology of CPF cell dewatering and residue.....	38
Table 3.6	Water intake screen specifications.....	41
Table 3.7	Boiler water treatment chemicals.	42
Table 3.8	Hazardous Waste quantities generated and registered with the Province of Manitoba.....	45
Table 3.9	Summary of historic substance releases to air from the TANCO Mine (2000 – 2010), NPRI ID 2278, note all sulphuric acid is released as stack	48
Table 3.10	Summary breakdown of Particulate Matter (PM) releases to air (2006 - 2010); note that the significant increase PM releases beginning in 2007 as a result of the addition of road dust to the.....	48
Table 3.11	TANCO Baghouses and Dust Collectors.	48
Table 3.12	TANCO greenhouse gas emissions (2008).	49
Table 3.13	TANCO greenhouse gas emissions (2009).	49
Table 3.14	Tailings composition.....	50
Table 3.15	Annual conventional tailings.....	50
Table 3.16	Monthly mean concentrations of deleterious substances, pH range, total monthly effluent volumes and acute toxicity test results in the West	53
Table 3.17	Summary statistics of the TANCO Mine effluent characterization; 1997-2010. Units are mg/L unless otherwise noted. Shaded values exceed the applicable Manitoba Water Quality Standard,	57
Table 3.18	Exceedances of MMER authorized limits for deleterious substances	61
Table 4.1	Summary of historical meteorological data collected at Pinawa, MB (1978-2007) and Bissett, MB (1968-1997) (Environment Canada 2008).....	67
Table 4.2	Monthly prevailing wind conditions at Pinawa, MB (2003-2007) (Environment Canada 2008).....	67
Table 4.3	Rainfall intensity (mm) at Bissett, MB (1969-1984) (Environment Canada 2008).....	68
Table 4.4	Rainfall events for the local study area.	69
Table 4.5	Annual rainfall occurrence probability in the local study area.....	69
Table 4.6	Nested wells completed within the East TMA.	73
Table 4.7	Single wells completed within the East TMA.	74
Table 4.8	Plant species identified within the East TMA (Wardrop 2008).....	78
Table 4.9	Physical characteristics of Bernic Lake and its watershed (SEACOR 2003).	82

Table 4.10	Water quality in Bernic Lake; 1968 to 1975 and 2002 to 2010. Shaded values exceed the Manitoba Water Quality Standards, Objectives and Guidelines for the Protection of Aquatic Life (MWQSOG, Williamson 2002). See Figures 4.7 and 4.8 for sampling locations. Units are mg/L except as noted.	89
Table 4.11	Water quality in Tulabi Lake; 2005 to 2010. Shaded values exceed the Manitoba Water Quality Standards, Objectives and Guidelines for the Protection of Aquatic Life (MWQSOG; Williamson 2002).	92
Table 4.12	Dissolved metal concentrations (mg/L) in Bernic Lake; 2002 to 2010 (no data available for 1968 to 1975). Shaded values exceed the Manitoba Water Quality Standards, Objectives	94
Table 4.13	Dissolved metal concentrations (mg/L) in Tulabi Lake; 2005 to 2010. Shaded values exceed the Manitoba Water Quality Standards, Objectives and Guidelines for the Protection of Aquatic Life	97
Table 4.14	Total metal concentrations (mg/L) in Bernic Lake; 1975 and 2002 to 2010 (no data available for 1968 to 1970). Shaded values exceed the Manitoba Water Quality Standards, Objectives and Guidelines for the Protection of Aquatic Life (MWQSOG; Williamson 2002). See Figures 4.7 and 4.8 for sampling locations.	99
Table 4.15	Total metal concentrations (mg/L) in Tulabi Lake; 2005 to 2010. Shaded values exceed the Manitoba Water Quality Standards, Objectives and Guidelines for the Protection of Aquatic Life	102
Table 4.16	US EPA trophic state delineation (after US EPA 1974).	104
Table 4.17	Sediment quality for Bernic Lake near-field and far-field sample stations; October 2005 (n = 10) and October 2008 (n = 10). Values are mg/kg unless otherwise noted.	111
Table 4.18	Sediment quality for Tulabi Lake sample stations; October 2005 (n=10) and October 2008 (n=10). Values are mg/kg.	112
Table 4.19	Pre-development and immediate post	113
Table 4.20	Summary of benthos statistics for the far-field and near-field (exposure) gradients sampled in Bernic Lake, October 2002, 2005 and 2008.	116
Table 4.21	Summary of benthos statistics for Tulabi Lake, October 2005 and 2008.	118
Table 4.22	Fish species occurring in Bernic Lake as determined from gillnet and beach seine sampling, 9 to 13 September 1993 (TANCO unpub. data; Crowe 1969).	120
Table 4.23	Municipalities in the regional study area.	124
Table 4.24	Labour force distribution by industry for municipalities in the regional study area (Statistics Canada 2006).	124
Table 4.25	Five archaeological sites in the study area; UTM coordinates are in NAD83.	126
Table 4.26	Average annual and peak traffic volumes for PR 313 and 315 (MIT and UMTIG 2009)...	128
Table 6.1	Effluent Sampling Parameters	141
Table 6.2	Frequency of MMER sampling at the TANCO Mine.	141
Table 6.3	Parameters measured for effluent characterisation and water.	143
Table 6.4	Parameters for groundwater quality analyses.	146

LIST OF FIGURES

Figure 1.1	TANCO Mine Location at Bernic Lake, Manitoba.	3
Figure 1.2	Aerial view of the TANCO mine looking north, Lac du Bonnet, MB.....	6
Figure 2.1	TANCO Mine regional study area.	13
Figure 2.2	Bernic Lake watershed.	14
Figure 2.3	Project Site, represented by Surface Leases.	15
Figure 3.1	Mineral Leases.	17
Figure 3.2	Minesite Layout.....	20
Figure 3.3	Idealized mine cross section looking southwest.	27
Figure 3.4	Photograph showing the pH adjustment system at the West Discharge.....	33
Figure 3.5	Main Dam and Perimeter Dykes.	35
Figure 3.6	Estimated residue footprint at end of mine life.	39
Figure 4.1	Environment Canada meteorological station locations.	66
Figure 4.2	Windrose showing wind direction and speed at Pinawa from 2003-2007.	69
Figure 4.3	Inferred Potentiometric Map (September 2010).....	72
Figure 4.4	Forest cover adjacent to the minesite (Sept. 2009).	77
Figure 4.5	Natural vegetative establishment in the East (inactive) TMA (August 2008).....	77
Figure 4.6	Owl Flintstone Caribou Range.....	80
Figure 4.7	Bernic Lake bathymetry and historic (1969-1975) water quality sample stations.....	86
Figure 4.8	Bernic Lake water quality sample stations (2009).	87
Figure 4.9	Tulabi Lake water quality sample stations (2009).	88
Figure 4.10	Substrate distribution in the TANCO discharge bay of Bernic Lake (October 2005).....	107
Figure 4.11	Bernic Lake exposure sediment and zoobenthos sample stations (2005).	108
Figure 4.12	Bernic Lake near-field and far-field sediment and zoobenthos sample stations (2008).	109
Figure 4.13	Tulabi Lake sediment and zoobenthos sample stations (2008).....	110
Figure 4.14	Macrophyte distribution in the TANCO discharge bay of Bernic Lake (October 2005) lower trophic levels.....	119
Figure 4.15	Archaeological sites located within or near the local study area (MB Historical Resources Branch 2010); EcKu-28 and EcKu-31 are northeast of EcKu-29 on Bird River.	127