

APPENDIX G
PICTURES CLEANING OF DIFFUSERS DURING NOVEMBER 2013 SHOWING
EXTENT OF CONTAMINATION BY FOREIGN MATERIAL



First Header
From East

2nd header
from east





3rd header
from east



4th header from
east



7th header from east



8th header from
east



10th header from east



12th header
from east



5th header from east

6th header from east

